HAGERSTOWN LANDMARKS RECONNAISSANCE SURVEY

Maryland Inventory of Historic Properties # WA-HAG-191

Property Name/Address: Miller's House, Hager Park, Hagerstown, Maryland

Description/Significance: Inscribed 1791 S, D + M, and built of brick, it reflects the early prosperity of the town and its surrounding countryside linked with grist and flour milling. Although updated in the late 19th century (porches, first story windows, etc.), the house retains many features associated with early construction.¹

MARYLAND COMPREHENSIVE HISTORIC PRESERVATION PLAN DATA

I. Geographic Organization: Western Maryland

II. Chronological/Developmental Period(s):

Rural Agrarian Intensification, 1680-1815

III. Prehistoric/Historic Period Theme(s):

Architecture, Landscape Architecture and Community Planning

IV. Resource Type

Category: Building

Historic Environment: Urban Historic Function(s) and Use(s):

DOMESTIC/single dwelling Known Design Source: Unknown

Form Prepared by:

Peter E. Kurtze 109 Brandon Road

Baltimore, Maryland 21212

August 15, 1991

¹ Description/significance information prepared by Paula S. Reed, PhD, Architectural Historian, Preservation Associates, Inc., Hagerstown, Maryland.

Maryland Historical Trust State Historic Sites Inventory Form

DOE __yes __no

Magi No.

1. Nam	(indicate pro	eferred name)		
historic	-		er en	
and/or common	Mîller's Hous	e		
	ation	and the same of th		
street & number	Hager Park		_	_ not for publication
city, town Ha	agerstown	vicinity of	congressional district	
state Maryland		county	Washington	
3. Clas	sification			
Category district _X building(s) structure site object	Ownership X public private both Public Acquisition in process being considered not applicable	Status X occupied unoccupied work in progress Accessible X yes: restricted yes: unrestricted no	Present Use agriculture commercial educational entertainment government industrial military	museum X park private residence religious scientific transportation other:
4. Own	er of Prope	rty (give names an	nd mailing addresses	of <u>all</u> owners)
name Cit	y of Hagerstown			
street & number	City Hall		telephone no	.:
city, town	Hagerstown	state	and zip code Mary	land —
5. Loca	ation of Leg	al Description	on	
courthouse, regi	stry of deeds, etc. Wash	nington County Co	ourthouse	liber
street & number	95 West Washin	gtonStræt		folio
city, town Ha	agerstown		state	Maryland
6. Rep	resentation	in Existing	Historical Surve	eys
title n/a				
date			federal state	e county loca
pository for su	urvey records			
city, town			state	

7. Description

Condition excellent	deteriorated	Check one unaltered	Check oneX original site	
x good fair	ruins unexposed	_X_ altered	moved date of move	

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The building known as the Miller's House is a $2\frac{1}{2}$ story, gableroofed, side passage plan painted brick dwelling dated 1791. three-bay-wide principal facade faces east and is constructed of brick laid in Flemish bond, with a quarter-round water table of molded brick above a raised limestone foundation. The entrance, located in the northernmost bay, has a four-light transom above a replaced door. An early 20th century Colonial Revival porch spans the entrance bay, wraps around the north gable, and continues across the west elevation. The other first-floor bays hold tall two-overtwo sash (installed in the course of a late 19th century remodeling, in which the window openings were lengthened by lowering the sills to the level of the water table). The window openings retain splayed jack arches, two brick-lengths high. A cellar entrance (the opening has been reworked) is located below the central bay; to the left of this entrance is a blocked cellar window with a brick jack arch. On the second story, six-over-six sash survive in original pegged frames with backband trim, surmounted by rubbed brick jack arches. second story windows also retain projecting molded sills with coved subsills. The east facade is capped by a complex cornice with bed and crown moldings. The roof is covered with brown asphalt or fiberglass shingles; there are no dormers on the east slope.

The north gable wall is laid in three-course bond. There are no openings at the level of the first floor; a single window is located on the second floor, offset to the east of center. This opening retains a splayed jack arch, two brick-lengths high, but has been enlarged by lowering the sill a distance of approximately six courses. Two original 4/2 windows in pegged frames with backband molding light the gable.

The west elevation of the main block is laid in Flemish bond. The fenestration corresponds to that of the east facade, but all the openings on the west elevation were reworked and enlarged in the late 19th century. The entrance in the north bay was raised, and shifted about $1\frac{1}{2}$ foot to the south; a portion of the original two-brick-high splayed jack arch survives in the wall to the left of the present entrance to indicate the height and jamb location of the original opening. The window openings on both levels have been enlarged to accommodate late 19th century 2/2 sash. The boxed cornice with crown and bed moldings appears to have been replaced on this elevation.

(see Continuation Sheet 7.1)

Period prehi 1400 1500 1600 1700 1800 1900-	-1499 archeology-historic -1599 agriculture -1699X architecture -1799 art -1899 commerce	 community planning conservation economics education engineering exploration/settlement 	literature military music t philosophy politics/government	religion science sculpture social/ humanitarian theater transportation other (specify)
Specific	dates 1791	Builder/Architect U	nknown	
check:	Applicable Criteria:A and/or Applicable Exception: Level of Significance:	BCD:	_ _	
Prepare	both a summary paragraph			f history and

WA-HAG-191

Survey No.

8. Significance

alterations.

support.

The Miller's House in Hager Park is significant for its architecture, as a dated example of a type of dwelling occupied by a successful merchant during the early period of Hagerstown's development. Its fine Flemish bond brickwork and exterior detailing reflect the relative prosperity of the milling industry during this period, as well as that of the surrounding agricultural region which supported it. The building retains a good level of integrity despite

10. Geographica	l Data		
Acreage of nominated property Quadrangle name Hagerstown UTM References do NOT complet	<u>,</u> MD	es	Quadrangle scale 1:24,000
A Zone Easting Northin	<u> </u>	B Zone E	asting Northing
C		D	
Verbal boundary description and	ustification		
List all states and counties for pr	operties overlapp	ing state or coun	nty boundaries
state	code	county	code
state	code	county	code
11. Form Prepare	ed By		
name/title Peter E. Kurtze			
organization		date	August 15, 1991
street & number 109 Brandon	Road	telep	hone (301) 296-7538
city or town Baltimore		state	Maryland 21212

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust

Shaw House 21 State Circle

Annapolis, Maryland 21401

(301) 269-2438

WA-HAG-191 Miller's House Hagerstown, Washington County, Maryland

Continuation Sheet 7.1

Two gabled dormers mark the west slope of the roof; they appear to be new, or at least substantially reconstructed in the recent past.

A lower shed-roofed wing, two bays wide, extends from the south gable. The west wall of this wing is flush with that of the main block, but a construction seam is readily apparent, indicating that the two sections were not built contemporaneously. The west wall of the wing is two stories high; it is laid in Flemish bond on the ground level and common bond above. Both bays of the west wall of the wing hold windows on both stories; the north bay was formerly an entrance. All the windows are 6/6 sash in plain mitered frames; evidence of a former splayed jack arch at the south window on the first floor shows the degree to which the opening was enlarged.

A close inspection of the brickwork of the south end wall of the wing clearly indicates that it was raised to its present steep shed-roofed form from a previous 1½ story gable configuration. The change in the brickwork between what was formerly the west slope of the gable and the upper corner of the present wall is evident. There is also an apparent seam indicating the jamb of a small window opening in the peak of the former gable.

The east wall of the wing is laid in three-course bond. There is an entrance in the north bay and a 6/6 window in the south bay; both are located in unaltered openings with simple brick arches. The window retains its original pegged frame, but without the backband trim seen on the main block. The east wall of the wing is recessed behind the plane of the east facade of the main block; the steeply sloping shed roof extends to create a porch. The north end of the porch was enclosed in the early 20th century.

The form of the wing suggests that it predates the main block, and the Flemish bond of the west elevation further suggests that this was the primary facade. The building was reoriented to face east when the present main block was added.

The south gable end of the main block has a single 4/2 window in a pegged frame with backband centered on the second story, above the level of the wing's shed roof. An arched datestone set into the gable peak reads:

S D & M 1791

(see Continuation Sheet 7.2)

WA-HAG-191 Miller's House Hagerstown, Washington County, Maryland

Continuation Sheet 7.2

(the original owner remains unidentified at this writing). A large corbeled interior chimney rises above the south gable.

The interior was not accessible.

The house is owned by the City of Hagerstown and located within a small landscaped park.

WA-HAG-191 Miller's House Hagerstown, Washington County, Maryland

Continuation Sheet

MARYLAND COMPREHENSIVE HISTORIC PRESERVATION PLAN DATA

- I. Geographic Organization: Western Maryland
- II. Chronological/Developmental Period(s):
 Rural Agrarian Intensification, 1680-1815
- III. Prehistoric/Historic Period Theme(s):
 Architecture, Landscape Architecture and Community Planning
- IV. Resource Type


Category: Building

Historic Environment: Urban

Historic Function(s) and Use(s):

DOMESTIC/single dwelling

Known Design Source: Unknown





WA HAG-191

MILLER'S HOUSE

YHAGERSTONUN MO

TIGHT CORTEE

VIEW YROM HONTHUEST



MA-VAG-191
MILLER'S HOUSE
HAGERSTOWN, MD
191 P. KURTZE
EAST FACADE